



JOHN LYLE LACQUERED LINEN
CARE INSTRUCTIONS

Environment:

- 55' to 78' Fahrenheit
- 50% to 70% relative humidity
- No extreme fluctuations in temperature and humidity
- No proximity to direct heat sources
- Limited exposure to direct sunlight
- Moisture must be wiped dry as soon as possible

Wipe surface with a damp, soft cloth.
Buff with a soft clean cloth to restore lacquer shine.

Spots or sticky spills can be removed with a mild dish soap solution and a soft-bristled toothbrush. Dry immediately.

Lacquer pieces should be kept out of direct sunlight and away from extreme heat, which may cause the surface to fade and allow fine cracks to form. Once light and heat damage has occurred, other deterioration can happen as well, and the beauty and lifespan of your lacquer will be reduced.

Avoid oily polishes or chemicals, which can penetrate the surface of the lacquer and loosen the layers of underlying base mixture, causing it to crack or break off.